



HYUNDAI Technical Service Bulletin

Group	ENGINE MECHANICAL
Number	05-20-002
Date	JULY, 2005
Model	ALL MODELS

Subject
**USE OF AFTERMARKET ENGINE OIL FILTERS
 CAUSING ENGINE KNOCKING NOISE**

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

DESCRIPTION:

Some vehicles may experience an engine knock noise with the use of an aftermarket oil filter. Aftermarket oil filters may use different materials, construction and specifications than genuine Hyundai oil filters, which may lead to pressure variations within the engine, thus contributing to an engine knocking noise.

VEHICLES AFFECTED:

All Models

REPAIR PROCEDURE:

Perform an oil change on the vehicle and replace the aftermarket oil filter with a genuine Hyundai oil filter.

WARRANTY INFORMATION:

Normal warranty procedures apply.

This is not a warranty repair.